

# Trip Report

## Division of Oil and Gas Resources Management

---

---

**Trip Date:** 12-14-2016

**Location:** Belmont County

**Owner:** Austin Masters

**Weather:** Cold, snow, partly sunny, 24 degrees

**Arrival/Departure:** 10:20-10:55

**Attendees:** Anthony Carson (DOGRM), Troy Mazur, (Radiation Safety Officer, Austin Masters)

**Purpose of meeting:** Facility inspection

### **Inspection Findings:**

- The facility is operating. Facility Radiation Safety Officer gave me a walkthrough of the facility.
- Some changes of the area which in the past was being used for down blending is not the west portion of building where tanks have been stored.
- A new half round is on site and a new liner has been installed in the pit where half rounds are utilized.
- Site is operating as per chief's order.
- There were no issues to report at this time.

### **Recommendations:**

### **Photographs:**

- Pictures acquired.