

Trip Report

Division of Oil and Gas Resources Management

Trip Date: 09/16/2015

Location: Belmont County

Owner: Austin Masters

Weather: Sunny, 83° F

Arrival/Departure: 13:16 AM – 14:34 PM

Attendees: Jake Glascock, DOGRM, Melissa Smalley (EHS/Austin Masters), Jack Bement (Facility Manager/Austin Masters), Denny ? (Inspector/Claims/OSHA)

Purpose of meeting: Facility inspection

Inspection Findings:

- The facility is now in operation. Facility Manager, Jack Bement, of Austin Masters explained safety and process of treating waste.
- There were no issues to report at this time.

Recommendations:

- All material considered oil and gas waste treated or not, should be placed on or in a secondary containment within the primary containment.

Photographs:



Inside of facility from office above truck entrance.



Inside of facility looking down at storage containers



Railcars loaded or to be loaded with material to be shipped off to Energy Solutions for disposal of low level radioactive waste.



Solidification area for mixing solids with lime



Crew emptying and cleaning out storage container contents into 40 ton half round.



Down blended clean material ready to be shipped to West Virginia landfill.



One of several monitoring wells located outside and around the facility.